MIDAS HUB4 Firmware Update Version 2.3

(2020-04-17)

Welcome

Congratulations on purchasing this innovative personal monitoring system. This update introduces a wealth of new features that help simplifying setup, improve overview and provide new means of communication for all live performance and studio production applications, where musicians are in control of their own monitor mix.

Midas is constantly adding new features and making enhancements to this extremely stable ecosystem of digital mixers, I/O boxes and personal monitoring mixers. This means you always experience the best possible performance. Visit midasconsoles.com and check for updates of your products regularly. Download the latest firmware for DP48 and HUB4, and make sure the latest versions will be installed to both.

New Features 2.3

- DP48 Talkback-System
  - Updated Signal-Routing (see Routing-Diagram attached)
  - LED-Indication when Talkback is used
- Support DP48 Remote-Control on Sync-Port


Improvements

- Better AES50 error management and faster recovery

Firmware Update Process with SimplyPUT

1. Download SimplyPUT from midasconsoles.com (available for OSX, Windows and Linux)
2. Extract the archive and follow the on-screen instructions to install software
3. Connect HUB4 to computer via USB
4. Hold button [1] below 'PORT 1-4 TO OUTPUTS' while turning on HUB4
5. Keep pressing until all buttons [1] - [4] turn green
6. Open SimplyPUT Update-Tool and select most recent Firmware-Version from the drop-down menu
7. Press Update-Button to update firmware
8. Do not turn off the device before the update has finished
   (active Update is indicated by flashing Buttons [1] - [4])
9. After successful update restart HUB4 and detach USB-Connection

MIDAS HUB4
Routing+Talkback (08.04.2020)



musictribe.com