

Changelog

[3.1] - 2024-08-12

Added

- support for new PLL

Changes

- delayed phantom power-on (to avoid psu overload)

[3.0-1] - 2024-04-17

- files updated to fix surface/pad device not found issues

[3.0] - 2024-01-03

Added

- support for Wing protocol (use of Wing on both ports)